

# **Operation Manual**

## **GB-Series SSI**

Magnetostriktive Lineare Positionssensoren



### **Table of contents**

1.	Introduction	
	1.1 Purpose and use of this manual	3
	1.2 Used symbols and warnings	3
2.	Safety instructions	
	2.1 Intended use	
	2.2 Forseeable misuse	3
	2.3 Installation, commissioning and operation	4
	2.4 Safety instructions for use in explosion-hazardous areas	
	2.5 Warranty	4
	2.6 Return	
3.	Identification	
	3.1 Order code Temposonics® GB	5
	3.2 Nameplate (example)	
	3.3 Approvals	
	3.4 Scope of delivery	
4.	Product description and commissioning	
	4.1 Functionality and system design	
	4.2 Styles and installation of Temposonics® GB-J / GB-K / GB-N / GB-S	
	4.3 Styles and installation of Temposonics® GB-M / GB-T / GB-B	
	4.4 Magnet installation	
	4.5 Change orientation of sensor electronics housing	
	4.6 Replacement of base unit	
	4.7 Electrical connection	
	4.8 Frequently ordered accessories	
5.	Operation	18
	5.1 Getting started	18
	5.2 Programming and configuration	18
6.	Maintenance and troubleshooting	21
	6.1 Error conditions, troubleshooting	21
	6.2 Maintenance	21
	6.3 Repair	21
	6.4 List of spare parts	21
	6.5 Transport and storage	21
	Removal from service / dismantling	21
8.	Technical data	22
	8.1 Technical data GB-J / GB-K / GB-N / GB-S	22
	8.2 Technical data GB-M / GB-T	23
n	Annendix	2/

#### 1. Introduction

#### 1.1 Purpose and use of this manual

Before starting the operation of Temposonics® position sensors read this documentation thoroughly and follow the safety information. Keep the manual for future reference!

The content of this technical documentation and of its appendix is intended to provide information on mounting, installation and commissioning by qualified automation personnel <sup>1</sup> or instructed service technicians who are familiar with the project planning and dealing with Temposonics® sensors.

#### 1.2 Used symbols and warnings

Warnings are intended for your personal safety and for avoidance of damage to the described product or connected devices. In this documentation, safety information and warnings to avoid dangers that might affect the life and health of operating or service personnel or cause material damage are highlighted by the preceding pictogram, which is defined below.

SWIIIIII	n.,		15	_	
	15	4001	ш	[1]	

#### Meaning

NOTICE

This symbol is used to point to situations that may lead to material damage, but not to personal injury.

#### 2. Safety instructions


#### 2.1 Intended use


This product may be used only for the applications defined under item 1 and only in conjunction with the third-party devices and components recommended or approved by MTS Sensors. As a prerequisite of proper and safe operation, the product requires correct transport, storage, mounting and commissioning and must be operated with utmost care.

1. The sensor systems of all Temposonics® series are intended exclusively for measurement tasks encountered in industrial, commercial and laboratory applications. The sensors are considered as system accessories and must be connected to suitable evaluation electronics, e.g. a PLC, IPC, indicator or other electronic control unit.

#### 2.2 Forseeable misuse

Foreseeable misuse	Consequence		
Wrong sensor connection	The sensor will not work properly or can be damaged		
Operate the sensor out of the operating temperature range	No signal output The sensor can be damaged		
Power supply is out of the defined range	Signal output is wrong / no signal output / the sensor can be damaged		
Position measurement is influenced by an external magnetic field	Signal output is wrong		
Cables are damaged	Short circuit – the sensor can be destroyed / sensor does not respond		
Spacers are missing / installed in wrong order	Error in position measurement		
Wrong connection of ground / shield	Signal output is disturbed The electronics can be damaged		
Use of a magnet that is not certified by MTS Sensors	Error in position measurement		





- 1/ The term qualified technical personnel characterizes persons who:
  - are familiar with the safety concepts of automation technology applicable to the particular project,
  - are competent in the field of electromagnetic compatibility (EMC),
- · have received adequate training for commissioning and service operations
- are familiar with the operation of the device and know the information required for correct operation provided in the product documentation.

#### 2.3 Installation, commissioning and operation

The position sensors must be used only in technically safe condition. To maintain this condition and to ensure safe operation, installation, connection and service, work should only be performed by qualified technical personnel.

If danger of injury to persons or of damage to operating equipment is caused by sensor failure or malfunction, additional safety measures such as plausibility checks, limit switches, EMERGENCY STOP systems, protective devices etc. are required. In the event of trouble, shut down the sensor and protect it against accidental operation.

#### Safety instructions for commissioning

To maintain the sensor's operability, it is mandatory to follow the instructions given below.

- 1. Protect the sensor against mechanical damage during installation and operation.
- 2. Do not open or dismantle the sensor.
- 3. Connect the sensor very carefully and pay attention to the polarity of connections and power supply.
- 4. Use only approved power supplies.
- 5. It is indispensable to ensure that the specified permissible limit values of the sensor for operating voltage, environmental conditions, etc. are met.
- 6. Check the function of the sensor regularly and provide documentation of the checks.
- 7. Before applying power, ensure that nobody's safety is jeopardized by starting machines.

#### 2.4 Safety instructions for use in explosion-hazardous areas

The sensor is not suitable for operation in explosion-hazardous areas.

#### 2.5 Warranty

MTS Sensors grants a warranty period for the Temposonics® position sensors and supplied accessories relating to material defects and faults that occur despite correct use in accordance with the intended application ². The MTS Sensors obligation is limited to repair or replacement of any defective part of the unit. No warranty can be provided for defects that are due to improper use or above average stress of the product, as well as for wear parts.

Under no circumstances will MTS Sensors accept liability in the event of offense against the warranty rules, no matter if these have been assured or expected, even in case of fault or negligence of the company. MTS Sensors explicitly excludes any further warranties.

Neither the company's representatives, agents, dealers nor employees are authorized to increase or change the scope of warranty.

#### 2.6 Return

For diagnostic purposes, the sensor can be returned to MTS Sensors or a repair facility explicitly authorized by MTS Sensors. Any shipment cost is the responsibility of the sender <sup>2</sup>. For a corresponding form, see chapter "9. Appendix" on page 24.

<sup>2/</sup> See also applicable MTS Sensors terms of sales and delivery on www.mtssensors.com

#### 3. Identification

#### 3.2 2rder code Temposonics® GB

<b>G B</b>	3	4 5 6 7 8	9 12 11	12	13 14 15 16 17 18 19 <b>S</b>	22	21
a	?	С	d	е	f	g	h

#### a | Sensor model

G B Rod

#### 2 2esign

#### **GB** with threaded flange

- B Base unit for threaded flanges »M« and »T« (replacement only)
- Threaded flange with flat-face, M18×1.5-6g
- T Threaded flange with raised-face, 3/4"-16 UNF-3A

#### **GB** with pressure fit flange

- S 20using material stainless steel 2.4325 22ISI 3232, rod material stainless steel 2.43262 2.4322 22ISI 32422 Pressure fit flange Ø 18 mm, Ø 10 mm rod

c Stro@e length	Stro@e length				
2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	nm				
7   7   7   7   001.0128.0	) in.				
Standard stro2e length 2mm??	2rdering steps				
252 522 mm	5 mm				
5???? 75? mm	12 mm				
752212222 mm	25 mm				
12777225772 mm	52 mm				
252223252 mm	1272 mm				
Standard stro2e length 2in.22	2rdering steps				
12 22 in.	2.2 in.				
277 37 in.	2.5 in.				
322 42 in.	1.2 in.				
4??1??? in.	2.2 in.				
100128 in.	4.2 in.				

- 3/ The sensor in stainless steel 1.4404 (AISI 316L) is only available with following option:  $\boxed{\textbf{s}} (-40...+90 \, ^{\circ}\text{C} / -40...+194 \, ^{\circ}\text{F})$
- \*/ Non standard stroke lengths are available; must be encoded in 5 mm / 0.1 in. increments
- 4/ Encode in meters if using metric stroke length. Encode in feet if using US customary stroke length

d ②onnector type	
2 4 M12 male connector (8 pin) (Note the operating temperature of the connector)	
2 2 M16 male connector (7 pin) (Note the operating temperature of the connector)	
2 2 H01H10 (110 m) <sup>4</sup> XX m PUR cable (part no. 530 052) H03H33 (333 ft) <sup>4</sup> 22 ft PUR cable (part no. 530 052) (Note the operating temperature of the cable)	
T 2 2 T01T10 (110 m) 4 XX m Teflon® cable (part no. 530 112) T03T33 (333 ft) 4 22 ft Teflon® cable (part no. 530 112)	
2 2 V01V10 (110 m) 4 22 m Silicone cable (part no. 530 113) V03V33 (333 ft) 4 22 ft Silicone cable (part no. 530 113)	

f g h See next page

Trademarks and trade names mentioned in this document are those of their respective owners.

2 2ia cable

f	f 2utput							
	22242 2252 2262 2222 2222 2222							
	☑ Synchronous Serial Interface							
2a	ata length 22ox no. 242							
?	25	bit						
2	24 bit							
?u	tput	format 220x no. 252						
В	2in	ary						
G	Gra	ay						
Re	solu	tion 22ox no. 262						
?	?.?	™ mm						
2	?.?	11 mm						
3	2.25 mm							
4	②.1 mm							
5	2.22 mm							
?il	iltering performance 220x no. 222							
?	No filter							
2	Average filter 2							
3	Average filter 4							
4	Average filter 8							
?e	erformance 220x no. 22, 222							
?	?	Measuring direction forward, asynchronous measurement						
?	?	Measuring direction reverse, asynchronous measurement						
?	2	Measuring direction forward, synchronous measurement						
?	3	Measuring direction reverse, synchronous measurement						
g	②perating temperature							
?		0+100 °C (-40+212 °F)						
S	-40	0+90 °C (-40+194 °F)						
h	h   @rogramming							
11		ogramming						

#### 3.2 2 ameplate 2 example 2




Fig. 1: Example of a nameplate of a GB-S sensor

#### 3.3 2ppro2als

CE certification

#### 3.4 Scope of delinery

#### 

- Sensor
- O-ring
- 2 2ack-up ring

#### GB-2 GB-T (rod sensor with threaded flange)

- Sensor
- O-ring

#### GB-B (base unit for rod sensor with threaded flange)

Sensor

#### 4. 2 roduct description and commissioning

#### 4.2 2 unctionality and system design

#### 2 roduct designation

Position sensor Temposonics® GB-Series

#### Sensor model

- Temposonics® GB-J, GB-K, GB-N, GB-S, GB-M, GB-T (sensor rod)
- 2 Stroke length 252 3250 mm (1...128 in.)

#### **2utput signal**

2 SSI

#### **2pplication**

Temposonics® position sensors are used for measurement and conversion of the length (position) variable in the fields of automated systems and mechanical engineering.

#### 2 rinciple of operation and system construction

The absolute, linear position sensors provided by MTS Sensors rely on the company's proprietary Temposonics® magnetostrictive technology, which can determine position with a high level of precision and robustness. Each Temposonics® position sensor consists of a ferromagnetic waveguide, a position magnet, a strain pulse converter and supporting electronics. The magnet, connected to the object in motion in the application, generates a magnetic field at its location on the waveguide. A short current pulse is applied to the waveguide. This creates a momentary radial magnetic field and torsional strain on the waveguide. The momentary interaction of the magnetic fields releases a torsional strain pulse that propagates the length of the waveguide. Then the ultrasonic wave reaches the end of the waveguide it is converted into an electrical signal. Since the speed of the ultrasonic wave in the waveguide is precisely known, the time required to receive the return signal can be converted into a linear position measurement with both high accuracy and repeatability.




Fig. 2: Time-of-flight based magnetostrictive position sensing principle

#### **20 dular mechanical and electronic construction**

- The sensor rod protects the inner sensor element.
- The sensor electronics housing, a rugged stainless steel construction, contains the complete electronic interface with active signal conditioning.
- The external position magnet is a permanent magnet. Mounted on the mobile machine part, it travels along the sensor rod and triggers the measurement through the sensor rod wall.
- The sensor can be directly connected to a control system. Its electronics generates a position signal output proportional to the start and end of the active measuring range.

#### 4.2 Styles and installation of Temposonics® GB-2 2 GB-2 2 GB-3 2 GB-3 rod sensor with pressure fit flange)




Fig. 3: Temposonics\* GB-N / GB-S / GB-K / GB-J

#### Installation of GB with pressure fit flange

Mount the sensor via pressure fit flange through the bores in the sensor electronics housing with 6 machine screws  $M6\times16$  A2-70 (ISO 4762).




Fig. 4: Installation of GB with pressure fit flange »S« & »N«

#### Installation of a rod-style sensor in a hydraulic cylinder

The rod-style version has been developed for direct stroke measurement in a hydraulic cylinder. Mount the sensor through the bores in the sensor electronics housing with 6 machine screws  $M6\times16$  A2-70 (ISO 4762).

- Mounted on the face of the piston, the position magnet travels over the rod without touching it and indicates the exact position through the rod wall – independent of the hydraulic fluid.
- The pressure resistant sensor rod is installed into a bore in the piston rod.




Fig. 5: Sensor in cylinder

#### 2ydraulics sealing

Seal the flange contact surface via 0-ring in the undercut as shown in Fig. 6.

For pressure fit flange Ø18 f7 (GB-K / GB-N / GB-S):

0-ring  $15 \times 2$  mm (0.59 x 0.02 in.) (part no. 560 853)

For pressure fit flange Ø21 f6 (GB-J):

0-Ring  $17 \times 2$  mm (0.67 x 0.02 in.) (part no. 561 438)




Fig. 6: Sealing

- 2 Note the fastening torque of machine screws of 6 Nm.
- Seat the flange contact surface completely on the cylinder mounting surface.
- The cylinder manufacturer determines the pressure-resistant gasket (copper gasket, O-ring, etc.).
- The position magnet should not grind on the sensor rod.
- ☑ The piston rod drilling (GB-N / GB-S:  $\geq$  Ø 13 mm ( $\geq$  Ø 0.52 in.), GB-J / GB-K:  $\geq$  Ø 16 mm ( $\geq$  Ø 0.63 in.)) depends on the pressure and piston speed.
- Adhere to the information relating to operating pressure.
- Protect the sensor rod against wear.

#### 4.3 Styles and installation of Temposonics® GB-2 @ GB-T @ GB-B(rod sensor with threaded flange)




Fig. 7: Temposonics® GB-M / GB-T




Fig. 8: Temposonics® GB-B

#### Installation of GB with threaded flange »M« & »T«

Fix the sensor rod via threaded flange M18×1.5-6g or 3/4"-16 UNF-3A.




Fig. 9: Mounting example of threaded flange »M« & »T«

#### Installation of a rod-style sensor in a hydraulic cylinder

The rod-style version has been developed for direct stroke measurement in a hydraulic cylinder. Mount the sensor via threaded flange.

- Mounted on the face of the piston, the position magnet travels over the rod without touching it and indicates the exact position through the rod wall – independent of the hydraulic fluid.
- The pressure resistant sensor rod is installed into a bore in the piston rod.
- The base unit is mounted by means of only three screws. It is the only part that needs to be replaced if servicing is required, i.e. the hydraulic circuit remains closed. For more information see chapter "4.6 Replacement of base unit" on page 14.

#### NOTICE

The orientation of the sensor electronics housing respectively of the electrical connection of sensor models GB-M and GB-T can be changed after mounting. For more information see chapter "4.5 Change orientation of sensor electronics housing" on page 14.




Fig. 10: Sensor in cylinder

#### 2ydraulics sealing

There are two ways for sealing the flange contact surface (Fig. 11):

1. A sealing by using an O-ring (e.g.  $22.4 \times 2.65$  mm (0.88  $\times$  0.1 in.)) in a cylinder end cap groove.



2. A sealing via an O-ring in the undercut.

For threaded flange (34"-16 UNF-3A) (GB-T):

0-ring  $16.4 \times 2.2 \text{ mm} (0.65 \times 0.09 \text{ in.}) \text{ (part no. 560 315)}$ 

For threaded flange (M18×1.5-6g) (GB-T):

0-ring  $15.3 \times 2.2 \text{ mm}$  (0.60 × 0.09 in.) (part no. 401 133)

In the case of threaded flange M18×1.5-6g, a screw hole based on ISO 6149-1 (Fig. 12) must be provided. See ISO 6149-1 for further information.




Fig. 11: Possibilities of sealing



- 2 Note the fastening torque of 50 Nm.
- Seat the flange contact surface completely on the cylinder mounting surface.
- The cylinder manufacturer determines the pressure-resistant gasket (copper gasket, O-ring, etc.).
- The position magnet should not grind on the sensor rod.
- ☑ The piston rod drilling ( $\geq$  Ø 13 mm ( $\geq$  Ø 0.52 in.)) depends on the pressure and piston speed.
- Adhere to the information relating to operating pressure.
- Protect the sensor rod against wear.

#### Notice for metric threaded flange




Fig. 12: Notice for threaded flange M18×1.5-6g based on DIN ISO 6149-1

#### 4.4 @agnet instal lation

#### Typical use of magnets




Fig. 13: Typical use of ring magnets and U-magnets

#### 2 ounting ring magnets and 2-magnets

Install the magnet using non-magnetic material for mounting device, screws, spacers etc.. The magnet must not grind on the sensor rod. Alignment errors are compensated via the air gap.

- Permissible surface pressure: Max. 40 N/mm²
- Fastening torque for M4 screws: 1 Nm; use washer, if necessary
- Minimum distance between position magnet and any magnetic material has to be 15 mm (0.6 in.) (Fig. 15).
- If no other option exists and magnetic material is used, observe the specified dimensions (Fig. 15).

#### NOTICE

Mount ring magnets and U-magnets concentrically. Do not exceed the maximum acceptable gap.




Fig. 14: Mounting of U-magnet, part no. 251 416-2

#### 2 agnet mounting 2 ith magnetic material

Then using magnetic material the dimensions of Fig. 15 must be observed.

- A. If the position magnet aligns with the drilled piston rod
- **B.** If the position magnet is set further into the drilled piston rod, install another non-magnetic spacer (e.g. part no. 400 633) above the magnet.




Fig. 15: Installation with magnetic material

#### Sensors with stroke lengths ≥ 1 meter (3.3 ft.)

Support horizontally installed sensors with a stroke length from 1 meter mechanically at the rod end. Dithout the use of a support, rod and position magnet may be damaged. A false measurement result is also possible. Donger rods require evenly distributed mechanical support over the entire length (e.g. part no. 561 481). Use an U-magnet (Fig. 16) for measurement.




Fig. 16: Example of sensor support

#### 2cti2e measuring range

The technical data of each sensor is checked as well as documented and the active stroke length (useful electrical stroke) with its start and end position is adjusted during final inspection and testing (Fig. 17). To ensure that the entire measuring range can be used electrically, the position magnet must be mounted mechanically as follows:




Fig. 17: Active measuring range

#### NOTICE

On all sensors, the areas left and right of the active stroke length are provided for null and dead zone. These zones should not be used for measurement, however the active stroke length can be exceeded.

#### 4.5 Thange orientation of sensor electronics housing

The orientation of the sensor electronics housing respectively of the electrical connection of sensor models GB-M and GB-T can be changed after mounting. Follow the instructions in Fig. 18.




Fig. 18: Align sensor electronics housing respectively electrical connection of GB-M / GB-T

#### 4.6 Replacement of 2ase unit

The base unit of the sensor models GB-M and GB-T is replaceable as shown in Fig. 19. The sensor can be replaced without interrupting the hydraulic circuit.




Fig. 19: Replacement of the base unit (GB-B)

#### 4.2 2 lectrical connection

Placement of installation and cabling have decisive influence on the sensor's electromagnetic compatibility (EMC). Hence correct installation of this active electronic system and the EMC of the entire system must be ensured by using suitable metal connectors, shielded cables and grounding. Overvoltages or faulty connections can damage the sensor electronics despite protection against wrong polarity.

#### NOTICE

- ② Do not mount the sensors in the area of strong magnetic or electric noise fields.
- Never connect / disconnect the sensor when voltage is applied.

#### Instruction for connection

- Use low-resistance twisted pair and shielded cables. Connect the shield to ground externally via the controller equipment.
- ② Deep control and signal leads separate from power cables and sufficiently far away from motor cables, frequency inverters, valve lines, relays, etc..
- Use only metal connectors and connect the shielding to the connector housing.
- ② Deep the connection surface at both shielding ends as large as possible. Connect the cable clamps to function as a ground.
- 2 Deep all non-shielded leads as short as possible.
- ② ②eep the ground connections short and with a large cross section. Avoid ground loops.
- ② ②ith potential differences between machine and electronics earth connections, no compensating currents are allowed to flow across the cable shielding.
  - Recommendation: Install potential compensating leads with large cross section, or use cables with separate double shielding, and connect only one end of the shield.
- Use only stabilized power supplies and make sure that the specified connecting values are met.

#### **Grounding of rod sensors**

Connect the sensor electronics housing to the machine ground via pressure fit flange respectively via threaded flange.

#### 2onnector 2iring

Connect the sensor directly to the control system, indicator or other evaluating systems as follows:




Fig. 20: Connector wiring D84 (M12)




Fig. 21: Connector wiring D70 (M16)







Fig. 22: Connector wiring cable outlet


#### 4.2 @re@uently ordered accessories @ Additional options available in our Accessories Guide [] 551 444

#### **2** osition magnets









#### Ring magnet 2233 2art no. 222 542-2

Material: PA ferrite GF20 Weight: Approx. 14 g Surface pressure: Max. 40 N/mm<sup>2</sup> Fastening torque for M4 screws: 1 Nm Operating temperature: -40...+105 °C (-40...+221 °F)

Ø 4.5 (Ø 0.18)

#### Ring magnet 2225.4 2art no. 422 533

Material: PA ferrite Weight: Approx. 10 g Surface pressure: Max. 40 N/mm<sup>2</sup> Operating temperature: -40...+105 °C (-40...+221 °F)

#### 2-magnet 2233 2art no. 252 426-2

Material: PA ferrite GF20 Weight: Approx. 11 g Surface pressure: Max. 40 N/mm<sup>2</sup> Fastening torque for M4 screws: 1 Nm Operating temperature: -40...+105 °C (-40...+221 °F)

#### Ring magnet 22 art no. 422 326

Bac2-up ring

Material: PA ferrite coated Weight: Approx. 13 g Surface pressure: Max. 20 N/mm<sup>2</sup> Operating temperature: -40...+100 °C (-40...+212 °F)

#### **2**osition magnet

Ø 63.5

(Ø 2.5)

Ø 42 (Ø 1.65)


Ø 16


 $(\emptyset \ 0.63)$ 


95

(0.37)

#### 2-rings







#### 2-magnet 2263.5 227 553 2art no. 222 553

Material: PA 66-GF30. magnets compound-filled Weight: Approx. 26 g Surface pressure: 20 N/mm<sup>2</sup> Fastening torque for M4 screws: 1 Nm Operating temperature: -40...+75 °C (-40...+167 °F)

#### O-ring for pressure fit flange Ø 18 mm 2art no. 562 253

Material: Fluoroelastomer Durometer: 75 Shore A

#### O-ring for pressure fit flange Ø 21 mm 2art no. 562 432

Material: FKM Durometer: 80 Shore A Operating temperature: -18...+200 °C (-0.4...+392 °F)


#### Back-up ring for pressure fit flange Ø 18 mm 2art no. 562 225


Material: PTFE + 60 % bronze


#### Bac2-up ring

#### 2ptional installation hard2are

#### 2 agnet spacer







#### Back-up ring for pressure fit flange Ø 21 mm

2art no. 562 432

Material: PTFE

#### Fixing clip for rod with Ø 10 mm 2art no. 562 422


Application: Used to secure sensor rods (Ø 10 mm (Ø 0.39 in.)) when using an U-magnet or block magnet Material: Brass, non-magnetic

#### 2 agnet spacer 2art no. 422 633

Material: Aluminum Weight: Approx. 5 g


Surface pressure: Max. 20 N/mm<sup>2</sup> Fastening torque for M4 screws: 1 Nm

#### 2a2le connectors 5




#### 2 22 2-coded female connector 22 pin2 straight 2art no. 322 624

Housing: GD-ZnAL
Termination: Screw
Contact insert: CuZn
Cable Ø: 4...9 mm (0.16...0.35 in.)
Wire: 0.75 mm²
Operating temperature:
-25...+90 °C (-13...+194 °F)
Ingress protection: IP67 (correctly fitted)
Fastening torque: 0.6 Nm




#### 2 22 2-coded female connector 22 pin2, angled 22 art no. 322 622

Housing: GD-ZnAL
Termination: Screw
Contact insert: CuZn
Cable Ø: 6...8 mm (0.24...0.31 in.)
Wire: 0.5 mm²
Operating temperature:
-25...+85 °C (-13...+185 °F)
Ingress protection: IP67 (correctly fitted)
Fastening torque: 0.6 Nm



#### 2 26 female connector 42 pin2, straight 2art no. 322 624

Material: Zinc nickel plated
Termination: Solder
Contact insert: Silver plated
Cable clamp: PG9
Cable Ø: 6...8 mm (0.24...0.31 in.)
Operating temperature:
-40...+100 °C (-40...+212 °F)
Ingress protection: IP65 / IP67
(correctly fitted)
Fastening torque: 0.7 Nm




## 226 female connector 22 pin2, angled 2art no. 562 222

Material: Zinc nickel plated
Termination: Solder
Contact insert: Silver plated
Cable Ø: 6...8 mm (0.24...0.31 in.)
Wire: 0.75 mm² (20 AWG)
Operating temperature:
-40...+95 °C (-40...+203 °F)
Ingress protection: IP67 (correctly fitted)
Fastening torque: 0.5 Nm

#### 2a2les

#### 2 rogramming tool



#### 22R ca2le 2art no. 532 252

Material: PUR jacket; orange Features: Twisted pair, shielded, highly flexible Cable Ø: 6.4 mm (0.25 in.) Cross section:  $3 \times 2 \times 0.25$  mm² Bending radius:  $5 \times \emptyset$  (fixed insulation) Operating temperature:



#### Teflon® ca2le 2art no. 532 222

Material: Teflon® jacket; black Features: Twisted pair, shielded, flexible Cable Ø: 7.6 mm (0.3 in.) Cross section:  $4 \times 2 \times 0.25$  mm² Bending radius:  $8 - 10 \times \emptyset$  (fixed installation) Operating temperature: -100...+180 °C (-148...+356 °F)



#### Silicone ca2le 2art no. 532 223

Material: Silicone jacket; red Features: Twisted pair, shielded, highly flexible Cable Ø: 7.2 mm (0.28 in.) Cross section: 3 × 2 × 0.25 mm² Bending radius: 5 × Ø (fixed installation) Operating temperature: -50...+180 °C (-58...+356 °F)



#### 2rogramming 2it 2art no. 254 522

Kit includes:

- 1 × interface converter box,
- 1 × power supply
- 1 × cable (60 cm) with M12 female connector (8 pin), straight – D-sub female connector (9 pin), straight
- 1 × cable (60 cm) with M16 female connector (7 pin), straight – D-sub female connector (9 pin), straight
- 1 × cable (60 cm) with 6 × terminal clamp 2 D-sub female connector (9 pin), straight
- 1 × USB cable

Software is available at: www.mtssensors.com

#### 5. 2 peration

#### 5.2 Getting started

The sensor is factory-set to its order sizes and adjusted, i.e. the distance between magnet and flange is specified in resolution steps.

Example: SSI value 4000 at the start of measuring range 40 mm with a resolution of 12 2m

**NOTICE** If necessary, the SSI sensors can be re-adjusted using the service tool described below.

#### **NOTICE**?

#### 22ser2e during commissioning

- Defore initial switch-on, check carefully if the sensor has been connected correctly.
- 2. Position the magnet in the measuring range of the sensor during first commissioning and after replacement of the magnet.
- 3. Ensure that the sensor control system cannot react in an uncontrolled way when switching on.
- 4. Ensure that the sensor is ready and in operation mode after switching on.
- 5. Check the pre-set span start and end values of the measuring range (Fig. 17) and correct them via the customer's control system if necessary, or via the MTS Sensors service tool. The operation of the service tool is described in detail on the following pages.

#### 5.2 Programming and configuration

#### SSI interface

The interface of Temposonics® position sensors corresponds to SSI industry standard for absolute encoders. Its displacement value is encoded in a 24 / 25 bit binary or gray format and transmitted RS422 compatible via 4 wires – independent of data width of the code (resolution).




Fig. 23: Schematic connection




Fig. 24: Input wiring clock (+) / clock (-)

The absolute, parallel position data is continually updated by the sensor and converted by the shift-register into a serial bit stream (Fig. 25).




Fig. 25: Timing diagram

This chapter describes "programming and configuration" of the GB SSI sensor via cable connection.

"Programming and configuration" via Bluetooth® connection are explained in document <u>551649</u>.

#### **TS Sensors programming tools**

Temposonics® position sensors can be adapted to modified measurement tasks very easily via the connecting leads ② without opening the sensor. For this, the MTS Sensors programming kit is available (see page 17).

#### Programming kit, part no. 254 592

The PC programmer is a hardware converter between sensor and serial PC interface. It can be used for adjusting sensor parameters via computer and the MTS Sensors programming software. The software for reading and adjusting the sensors requires a Dindows computer with a free USB port. You can adjust the following parameters:

- Data length and data format
- Resolution and measuring direction
- Synchronous / asynchronous measurement
- Measurement filter (moving average of 2, 4 or 8 measurements)
- ☐ Step 22 2onnect 22 programmer
- ☐ Step 2: Install software
- ☐ Step 3: Start programm
- Connect the PC programmer with the sensor via the corresponding adapter cable.
- Connect the PC programmer to a US<sup>®</sup> port of the computer.
- Connect the power supply via connector. The outer contact of the connector is 0 V (ground), the inner contact is 24 @DC.




Fig. 26: Connect PC programmer (example of GB-S / GB-N) (for sensors with cable outlet on the left, for sensors with connector outlet on the right)

#### **NOTICE**

Never connect / disconnect the sensor when voltage is applied.

- ✓ Step 1: Connect PC programmer
- ☐ Step 22 Instal soft2are
- ☐ Step 3: Start program

Download the current software version from www.mtssensors.com. Install the software .NET Framework as administrator. Copy the program GBS\_SSI\_Serial\_Configurator.exe to your computer and start it.

System requirements:

- 2 Microsoft 2 indows 7 operating system
- Microsoft .NET Framework from version 4.5.1 or higher
- ✓ Step 1: Connect PC programmer
- ✓ Step 2: Install software
- ☐ Step 3② Start program

After starting the program GBS SSI Serial Configurator the software connects to the last selected COM Port and the user interface opens (Fig. 29). If the COM Port is not available an error message appears (Fig. 27).




Fig. 27: Error message COM Port is not available

Select the right COM Port from the list (example see Fig. 28). The application will automatically restart and the user interface opens (Fig. 29).




Fig. 28: Select COM Port

#### GB SSI soft@are user interface




Fig. 29: User interface GB Serial Configurator

- Sensor Information contains the invariable sensor parameters, which were read in automatically when the sensor is connected.
- 2 In the **DeDice Settings** menu the configurable parameters (SSI Settings, Error Settings) of the sensor can be set.
- 3 The Deasurement menu shows the current position of the magnet.
- 4 The Sane button saves any parameter changes you have made. After that the software restarts for the changes to take effect. The function neasurement 3 will then be available again.
- **⑤** The button **②isconnect** breaks the connection to the COM Port and closes the software.
- **6** Dy clicking **Report** a report document is generated to provide sensor information.
- 1 The Dile menu allows the following settings (see also Fig. 29):
  - 1. pen: Uploads device settings from a XML file to the sensor. Click the Saze button 4 to complete the upload
  - 2. Sale as: Saves the current device settings as XML file
  - 3. Restore ②actory Settings: Restores and saves the sensor's factory settings
  - 4. **②lose**: Closes the software application without saving any parameters

#### 2e2ice Settings

The following parameters can be modified:

SSI Settings (Fig. 29)

Format: Binary / Gray
Data Length: 24 2its / 25 2its

Resolution: **5** 2**m** / 22 2**m** / **5**2 2**m** / 222 2**m** 

In asynchronous mode the sensor starts

measuring and provides the position independent

of the P2C. **Synchron**:

In synchronous mode the output of the Temposonics® SSI sensor is matched to the data request cycle of the

controller.

Direction: 2or2ard:

Ascending position values from sensor electronics

housing to rod end

Re2erse:

Ascending position values from rod end to sensor

electronics housing

Filter: 20 2ilter / 2ilter 22g. 2 / 2ilter 22g. 4 / 2ilter 22g. 2

Moving average of 2, 4 or 8 measurements for noise

reduction

Error Settings (Fig. 30)

Error Counter: 1
Error Value: 0

The ②rror ②ounter and ②rror ②alue settings determine, how often an error has to occur (②rror ②ounter) so that a certain ②rror ②alue is shown. The standard settings for the ②rror ②ounter is "1" and for the ②rror ②alue it is "2". So every error is shown with an error value of "2". ②oth parameters are changeable.




Fig. 30: Error Settings

#### **@easurement**

After clicking the **Start Read** button the current position of the magnet is shown. Click the **Stop Read** button to stop the measurement (Fig. 31). The **DieD** button provides a graphic display of the magnets position (Fig. 32).



Fig. 31: Display of current magnet position




Fig. 32: Data display

### 6. 2aintenanc e and trou2leshooting

#### 6.2 2rror conditions, trou2leshooting

2rror condition	Status
Magnet not detected	@efault error @alue@ @
	<b>2dapted error 2alue2</b>
	2216777215
	(see Fig. 30)
2 rong quantity of magnets	@efault error @alue@ @
	<b>2dapted error 2alue</b> 2
	2216777215
	(see Fig. 30)

#### 6.2 2aintenance

The sensor is maintenance-free.

#### 6.3 Repair

Repairs of the sensor may only be performed by MTS Sensors or an explicitly authorized body.

#### 6.4 2ist of spare parts

No spare parts are available for this sensor.

#### 6.5 Transport and storage

The conditions of transport and storage of the sensor match the operating conditions mentioned in this document.

### 2. Remo2al from ser2ice 2dismantling

The product contains electronic components and must be disposed of in accordance with the local regulations.

#### 2. Technical data

2 2 Technical	data	GB-22GB-22GB-22CGB	2_5
M.M Ittillital	uala	I GD-MAGD-MAGD-MAG	ט־נ

2utput

Interface SSI (Synchronous Serial Interface) – Differential signal in SSI standard

Data format ②inary, gray

Programming Programming of set points using optional accessories

Measured value Position

**2** easurement parameters

Resolution 5 @m minimum

Cycle time Up to 3.7 kHz depending on stroke length  $2 = \pm 0.02 \%$  F.S. (minimum  $\pm 60 \mu$ m) typical Repeatability  $\pm \pm 0.005 \%$  F.S. (minimum  $\pm 20 \mu$ m) typical

**2**perating conditions

Operating temperature -40...+90 °C (-40...+194 °F), option: -40...+100 °C (-40...+212 °F)

Ingress protection IP67 (if mating connectors are correctly fitted)

IP68 (for cable outlet)

Shock test 100 g (single shock) IEC standard 60068-2-27

Dibration test 15 g / 10...2000 Hz IEC standard 60068-2-6 (excluding resonant frequencies)

EMC test Electromagnetic emission according to EN 61000-6-4

Electromagnetic immunity according to EN 61000-6-2

The sensor meets the requirements of the EU directives and is marked with  $\mathbf{C} \in \mathbf{C}$ 

Operating pressure 350 bar (5,076 psi), 700 bar (10,153 psi) peak (at 10 × 1 min), GB-J: 800 bar (11,603 psi)

Magnet movement velocity Any

2 esign 2 2 aterial

Sensor electronics housing with flange GB-J / GB-K / GB-S: Stainless steel 1.4305 (AISI 303)

GB-N: Stainless steel 1.4404 (AISI 316L)

Sensor rod GB-J: Stainless steel 1.4301 (AISI 304)

GB-K / GB-S: Stainless steel 1.4306; 1.4307 (AISI 304L)

GB-N: Stainless steel 1.4404 (AISI 316L)

Stroke length 25...3250 mm (1...128 in.)

**@echanical mounting** 

Mounting position Any

Mounting instruction Please consult the technical drawings on page 8

**2lectrical connection** 

Connection type M12 A-coded male connector (8 pin); M16 male connector (7 pin); Cable outlet

Operating voltage +24 VDC (-15 / +20 %)

Ripple  $\leq 0.28 \text{ V}_{PP}$  Current consumption 92 mA typical

Dielectric strength 500 VDC (DC ground to machine ground)

Polarity protection Up to -30 VDC Overvoltage protection Up to 36 2DC

<sup>6/ 2</sup>ith position magnet 2 251 416-2

© 2 Technical data CD © GCD T	
2.2 Technical data GB-2 2GB-T	
<b>Output</b>	
Interface	SSI (Synchronous Serial Interface) – Differential signal in SSI standard
Data format	②inary, gray
Programming	Programming of set points using optional accessories
Measured value	Position
②easurement parameters	
Resolution	5 @m minimum
Cycle time	Up to 3.7 kHz depending on stroke length
②inearity <sup>®</sup>	$\leq$ ±0.02 % F.S. (minimum ±60 µm) typical
Repeatability	≤ ±0.005 % F.S. (minimum ±20 µm) typical
2 perating conditions	
Operating temperature	-40+90 °C (-40+194 °F), option: -40+100 °C (-40+212 °F)
Ingress protection	IP67 (if mating connectors are correctly fitted) IP68 (for cable outlet)
Shock test	100 g (single shock) IEC standard 60068-2-27
②ibration test	15 g / 102000 Hz IEC standard 60068-2-6 (excluding resonant frequencies)
EMC test	Electromagnetic emission according to EN 61000-6-4 Electromagnetic immunity according to EN 61000-6-2 The sensor meets the requirements of the EU directives and is marked with C €
Operating pressure	350 bar (5076 psi), 700 bar (10,153 psi) peak (at 10 × 1 min)
Magnet movement velocity	Any
2esign 2 2aterial	
Sensor electronics housing <sup>™</sup> with flange	Stainless steel 1.4305 (AISI 303)
Sensor rod	Stainless steel 1.4306 / 1.4307 (AISI 304L)
Stroke length	253250 mm (1128 in.)
2 echanical mounting	
Mounting position	Any
Mounting instruction	Please consult the technical drawings on page 12
2lectrical connection	
Connection type	M12 A-coded male connector (8 pin); M16 male connector (7 pin); Cable outlet
Operating voltage	+24 VDC (-15 / +20 %)
Ripple	$\leq 0.28 V_{pp}$
Current consumption	912 mA typical
Dielectric strength	500 VDC (DC ground to machine ground)
Polarity protection	Up to –30 VDC

Overvoltage protection

Up to 36 2DC

<sup>8/ 2</sup>ith position magnet 2 251 416-2



### 2. 2ppendix

### Safety 2eclaration

58513 Lüdenscheid, Germany www.mtssensors.com

Dear Customer,

If you return one or several sensors for checking or repair, we need you to sign a safety declaration. The purpose of this declaration is to ensure that the returned items do not contain residues of harmful substances and / or that people handling these items will not be in danger.

MTS Sensors order number:			Sensor type(s):		
Serial number(s):			Sensor length(s):		
The sensor has @een	in contact 2ith the follo	ling materials?			
Don@t specify chemica Please include safety of	al formulas. data sheets of the substar	nces, if applicable.		spected penetration of substances into the sensor, sors to determine measures to be taken before	
			shipment.		
Short description of n	nalfunction <sup>2</sup>				
②orporate information	1		②ontact partner		
Company:			Name:		
Address:			Phone:		
			E-Mail:		
	•	nt has been cleaned and no e to health risks during tr		excluded.	
Stamp	Signature			Date	
G?R????? 2TS Sensor T echnologie GmbH & Co.KG Auf dem Sch?ffel 9	Tel. +49-23 51-95 87 0 Fax. 249-23 51-5 64 91 info.de2mtssensors.com	©S© ©TS Systems ©orporation Sensors ©i©ision 3©©1 Sheldon Drive	Tel. 21 919 677-2122 Fax 21 919 677-2222 info.us2mtssensors.co	m	

www.mtssensors.com

Cary, N.C. 27513, USA



??**IT**?? **ST** ?**T**?**S** 3??1 Sheldon Drive **Temposonics**, 222 Cary, 2.C. 27513 Americas 2 APAC 2 egion Phone 2 2 1919 677-2 1 2 2

2-mail2 info.us2temposonics.com

**G**?**R**???? Auf dem Sch@ffel 9 Temposonics 52513 222denscheid Gm??? ? ?o. ?G Phone? 2492351 9527-? 2M2A 2egion 2 India 2-mail2 info.de2temposonics.com

T??? Phone? 2392329223219

Branch Office 2-mail2 info.it2temposonics.com

?**R**???? Phone? 2336 14 262 722 Branch Office 2-mail2 info.fr2temposonics.com

?!? Phone? 244 79 44 15 23 2? Branch Office 2-mail2 info.uk2temposonics.com

\$????!?? ?!? Phone? 246 72 29 91 221 Branch Office 2-mail2 info.sca2temposonics.com

??! ?? Phone? 22621 2415 1222 22415 1221 Branch Office 2-mail2 info.cn2temposonics.com

?????? Phone? ??13 6416 1263 Branch Office 2-mail2 info.jp2temposonics.com ?ocument ?art ?um?er?

551631 2evision C 2222 2722212







## temposonics.com